

CHING-suprALVITE-micaceous-top coat SAD 00-HS VA P

Intended use

Low-solvent, diffusion-tight, micaceous-iron-containing top coat with barrier protection for system structures with SAD 182-HS VA P.

Application

Chemical plants, pipe bridges, catenary support, lattice towers, transformer substations, transmission towers, and others.

General information

	Color shades	RAL- and DB-colors as well as further colors on request				
	Gloss	mat				
	Stirring / Dilution	Stir the product mechanically before each use. Ready to use after adding hardener. Dilute with CHING-Thinner S 08 if necessary.				
	Spraying	Viscosity [DIN 4]	Thinner [%]	Nozzle [mm]	Pressure [bar]	
	Cup gun	50 - 70 s	5 - 10	1,5 - 2,5	4 - 5	
	Airless (Airmix)	Delivery form	≤ 3	0,31 - 0,51	120 -200	
	Brush application	Delivery form				
	Roller application	Delivery form (minimum layer thicknesses have to be expected)				
	Flow application	n.a.				
	Substrate preparation	according to DIN EN ISO 12944-4; surface clean, dry, free of dust, salt, oil and grease as well as free of adhesion-reducing substances (e.g. corrosion products)				
	Drying time¹	Temperature	Dust-dry	Grip resistant	Mech. resilient	Recoatable²
	at 80 µm	NC 23/50	1 h	4 - 6 h	8 - 10 h	24 h
<p>¹ Based on delivery viscosity! Humidity has a decisive influence on drying!</p> <p>² with itself (not normally required for top and final coats, except possibly for minimum coat thicknesses)</p>						

	Viscosity delivery form	700 - 900 mPas				
	Other values	Density [g/cm ³] 1,4 ± 0,1	Solids [Weight. %] 73 ± 5	Solid volume [%] 55 ± 5	[cm ³ /kg] 380 ± 20	Efficiency¹ [m ² /kg] 4,7
		WFF 1,8	DFT² [µm] 80 - 100	Consume [g/m ²] 210 ± 20	VOC-content [g/l] (± 20) 410	Temperature resistance³ 70°C
These values are imputed values that may vary depending on the color shade and application. Drying times are correspondingly longer for thicker layers. The drying times are shortened by forced drying. ¹ ± 0,5 for 80 µm dry layer thickness (depending on shade) ² With layer thicknesses > - µm bubbles may form! ³ Dry heat						
	Notes	<ul style="list-style-type: none"> • Storage 18 months (in unopened original container. Store cool but frost protected!) • Processing conditions <ul style="list-style-type: none"> ❖ The air and object temperature should be at +10°C to +45°C (optimally at 15-35 °C) and the relative humidity at max. 80 %. The surface temperature of the parts to be coated must be at least 3 °C above the dew point of the surrounding air during application. ❖ Sufficient supply and exhaust air must be provided. 				